

MGNREGS

1. Date of inspection :- 17-01-2017
2. Team of Officers :- Shri D.S.Kharpan, Asstt. Director, Shri N.R. Kharchandy, Research Officer, Shri M.C..Khonglah, Research Asst. accompanied by Shri Jaseng P.Marak, JE, Gambegre Development Block.
3. Village:- Balamagre
4. Block:- Gambegre Development Block
5. Scheme :- Improvement of Playground at Balamagre.
6. Amount sanctioned :- Rs. 4,04,696/-
7. Year of sanctioned :- 2014-15
8. Date of commencement of the work:- 21-04-2014
9. Date of completion :- 27-11-2014
10. Expenditure incurred :-
 - i. Wages :- = Rs. 4,02,696/-
 - ii. Cost of materials :- =Rs. 2000/-
 - Total =Rs. 4,04,696/-
11. No. of labourers :- 46 (forty six)
Registered Jobcard households.
12. No. of Mandays: 2632
13. Implementing agency: Village Employment Council (VEC), Balamagre
14. Total length of the Playground:- 70.00 meters
15. Width of the playground:- 45.00 meters
16. Status of the work :- Completed
17. Quality of the work :- Good
18. Observation/findings:- It was found that Improvement and maintenance of the Playground is satisfactory.



An improved Playground




A sign board

INSPECTION ON MGNREGS SCHEME UNDER GAMBEGRE C& RD BLOCK

1. Date of inspection :- 17-01-2017
2. Village:- Balamagre
3. Block:- Gambegre Development Block
4. Scheme :- Construction of a Road from Balamagre Playground to Abimang
5. Nature of the scheme :- Ongoing Scheme
6. Amount sanctioned :- Rs. 3,77,000/-
7. Year of sanctioned :- 2015-16
8. Date of commencement of the work:- 19-05-2014
9. Date of completion :- 31-03-2016
10. Expenditure incurred :-
 - i. Wages :- = Rs. 3,74,900/-
 - ii. Cost of materials : = Rs. 2,000/-
 - Total = Rs. 3,76,900/-
11. No. of labourers :- 46 (forty six) Registered Jobcard households
12. No. of Mandays :- 2300
13. Implementing agency: Village Employment Council (VEC), Balamagre
14. Total Length of the road completed:- 1.00 Km
15. Width of the road:- 4.00 mts
16. Status of the work :- Completed
17. Quality of the work :- Good
18. Observation/findings:- It was observed that the quality of the road is good.



A Kutchha Road




A sign board

MGNREGS

1. Date of inspection :- 17-01-2017
2. Team of Officers :-
Shri D.S. Kharpan, Assistant Director, Shri N.R. Kharchandy, Research Officer, Shri M.C. Khonglah, Research Assistant, accompanied by Ananta Sangma (JE), Smt.Kilchena Marak (T/A) and Smt. Thisthinna Marak (T/A).
3. Name of the village:- New Harigaon
4. Name of the Block:- Selsella Development Block
5. Scheme :- Construction of CC Jeepable road from NEC road to new Harigaon.
6. Amount sanctioned :- Rs. 5,48,800/-
7. Year of sanctioned :- 2016-17
8. Date of commencement of the work:- 28-09-2016
9. Date of completion :- 21-12-2016
10. Expenditure incurred :-
 - i. Wages :- =Rs. 2,02,800/-
 - ii. Cost of materials : = Rs. 3,46,000/-Total = Rs.5,48,800/-
11. No. of labourers :- 30 labourers
12. No. of Mandays:- 1200
13. Implementing agency:- Village Employment Council, Secretary.
14. Total length of the Playground:- 0.475 Km
15. Width of the road:- 3.80 meters
16. Status of the work :- Completed
17. Quality of the work :- Good



CC Jeepable Road



Sign Board

18. Observation/findings:- The inspection team found that construction of the CC Jeepable road is completed and the quality of work is good.

MGNREGS

1. Date of inspection :- 17-01-2017
2. Name of the village:- Sangkarigre
3. Name of the Block:- Selsella C&RD Block
4. Scheme :- Construction of Boulder Sausage at Sangkarigre.
5. Amount sanctioned :- Rs.11,62,480/-
6. Year of sanctioned :- 2016-17
7. Date of commencement of the work:- 22-09-2016
8. Date of completion :- 8-11-2016
9. Expenditure incurred :-
 - i. Wages :- = Rs. 6,62,480/-
 - ii. Cost of materials :- =Rs. 5,00,000/-
 - Total = Rs.11,62,480/-
10. No. of labourers :- 98
11. No. of Mandays:- 3920
12. Implementing agency:- Village Employment Council, Secretary.
13. Total length of the Embankment:- 53 meters
14. Width of the Embankment:- 1.4 meters
15. Status of the work :- Completed
16. Quality of the work :- Good
17. Observation/findings:- It was observed that construction of Boulder Sausage at the river embankment was carried out only in high risk area on the side of the river where erosion and leaching is likely to occur to prevent washing away of the soil.



Boulder Sausage under construction



MGNREGA

1. Date of inspection :- 17-1-2017
2. Name of the village:- Ganchenggre
3. Name of the Block:- Selsella C&RD Block
4. Name of the scheme:- Construction of Spring Chamber = 2 nos
5. Nature of the scheme(Spill over/ongoing schemes):
MGNREGS



Spring Chamber

2. Amount sanctioned:- Rs. 5,09,560/-
3. Year of sanctioned:- 2016-17
4. Date of commencement of the work:- 2016
5. Date of completion:- 27-9-2016
6. Expenditure incurred:
 - i) Wages: =Rs. 2,09,560/-
 - ii) Cost of Materials : =Rs. 3,00,000/-
 - iii) Total =Rs.5,09,560/-



6. No. of job card involved :- 31
7. No. of Mandays:- 1240
8. Implementing Agency:- VEC Secretary
9. Total Length of the spring chamber:- 5.7 Meters
10. Width of the spring:- 4.5 Meters
11. No. of labourers:- NA
12. Status of the work:- Completed
13. Quality of the work: - Good
14. Observations/Findings:- The inspection team found that construction of the 2 (two) Nos. of Spring Chambers are completed and the same have already been used by the villagers and the quality of work was good.



Sign Board

MGNREGA

1. Date of inspection : 17-1-2017
2. Name of the village: Haldibari
3. Name of the Block: Selsella C&RD Block
5. Scheme:- Construction of Vermi Compost Pit
=1 no.
4. Amount sanctioned:- Rs. 20177/-
5. Year of sanctioned: - 2016-17
6. Date of commencement of the work:- 2016
7. Date of completion:- 8-11-2016
8. Expenditure incurred:
 - i) Wages: = Rs. 7267/-
 - ii) Cost of Materials : =Rs.12,910/-
 - iii) Total =Rs.20,177/-
9. No. of labourers :- 1
10. No. of Mandays :- 43
11. Implementing Agency:- VEC, Secretary
12. Total Length of the Vermi Compost Pit: 3.6 mts
13. Width of the compost pit:- 1.5 meters
14. Status of the work:- Completed
15. Quality of the work:- Good
16. Observations/Findings:- The inspection team observed that construction of the Vermi Compost Pit is completed and the quality of work is satisfactory.



Vermi Compost Pit

