

M.G.N.R.E.G.S

1. Date of inspection : 18-01-2017
2. Village: Aranggre
3. Block:- Rongram Development Block
4. Scheme:- Road Construction from PWD road to Sropgre village.
6. Amount sanctioned: - Rs.1,19,450/-
7. Year of sanctioned:- 2013-14
8. Date of commencement of the work:- 9-04-2013




A kutchha Road

4. Date of completion: 18-05-2013
5. Expenditure incurred:-

i) Wages:-	= Rs. 1,17,450/-
ii) Cost of Materials : -	Rs. 2000/-
Total	= Rs.1,19,450/-

6. No. of Mandays:- 810
7. Implementing Agency: - DRDA
8. Total Length of the Road : - 1.5 Km
9. Width of the road:- 6 ft.
10. No. of labourers:- 29 (Households)
11. Status of the work:- Completed
12. Quality of the work:- Good



Sign board

13. Observations/Findings:- The inspection team found that the construction of a road from PWD road to Sropgre village is completed and the quality of work is good.

MGNREGA INSPECTION REPORT RONGRAM BLOCK

1. Date of inspection :- 18-01-2017
2. Village:- Srop A-dinggre
3. Block:- Rongram C & RD Block
4. Name of the scheme:- Construction of Road from PWD road to Srop A-Dinggre.
5. Amount sanctioned:- Rs. 2,05,000/-
6. Year of sanctioned:- 2013-14
7. Date of commencement of the work:- 9-04-2013
8. Date of completion:-18-05-2013
9. Expenditure incurred:-

- i) Wages:- =Rs.2,03,000/-
- ii) Cost of Materials : =Rs. 2,000/-
- Total = Rs.2,05,000/-

10. No. of Mandays:- 810 days
11. Implementing Agency:- VEC/AEC: Srop A-Dinggre
12. Total Length of the Road:-2.00 Km.
13. Width of the Road:- 6 Ft.
14. No. of labourers:- 27 households
15. Status of the work:- Completed
16. Quality of the work:- Good

18. Observations/Findings:- The inspection team found that construction of the said road is completed and the quality is good.



A completed kutchha road



Sign Board

M.G.N.R.E.G.S

1. Date of inspection :- 18-1-2017
2. Village:- Chidekgre
3. Block:- Rongram Development Block
4. Scheme:- Improvement of Playground at Chidekgre
5. Amount sanctioned:- Rs. 1,91,400/-
6. Year of sanctioned:- 2014-15
7. Date of commencement of the work:-22-10-2014
8. Date of completion:- 18-12-2014
9. Expenditure incurred:

- i) Wages:- =Rs. 1,91,400/-
- ii) Cost of Materials: Rs. 2000/-
- Total = Rs.1,93,400 /-

10. No. of Mandays:- 1320 days
11. Implementing Agency:- VEC, Secretary, Chidekgre
12. Total Length of the Playground:- 87 meters
13. Width of the Playground :- 40 meters
15. No. of labourers:- 40 households
16. Status of the work:- Completed

17. Quality of the work:- Good

18. Observations/Findings:- The inspection team found that there was a deference of the amount furnished by the Gramsevak-Cum-TA incharge with the one written on the sign board. On enquiry the said gramsevak informed that the amount shown on the sign board is wrong and the above mentioned amount given by him is a correct one. It was also found that improvement works of the Playground is completed and the quality of work is good.



Playground at Chidekgre



A Sign Board

M.G.N.R.E.G.S

1. Date of inspection :- 18-01-2017
2. Team of inspecting officers:-D.S Kharpan, Asstt Director, N. R Kharshandy, Research Officer, M.C Khonglah, Research Asstt. accompanied by Smt. Grensilla Ch.Marak (Gramsevika), Shri Julin Marak (Gramsevak)
3. Village:- Aranggre
4. Block:- Rongram C & RD Block



5. Scheme:- Construction of Dugout Fishery Pond, 1 No.

A Fishery Pond

6. Amount sanctioned:- Rs.1,78,040/-
7. Year of sanctioned:- 2015-16
8. Date of commencement of the work:-25-8-2015 to 11-10-2015
9. Date of completion:-11-11-2015
10. Expenditure incurred:-
 - i) Wages:- = Rs. 1,76,040/-
 - ii) Cost of Materials : = Rs. 2,000/-Total = Rs. 1,78,040/-



A Sign Board

11. No. of Mandays:- 1080 days
12. Implementing Agency:-DRDA
13. Total Length of the Dugout Fishery Pond:- 30 Meters
14. Width of the Dugout Fishery Pond:- 22 Meters
15. Depth of the pond:- 2 Meters
16. No. of labourers:- 27 households
17. Status of the work:- Completed
18. Quality of the work:- Good
19. Observations/Findings:- The inspection team found that construction/ digging of Fishery Pond is completed but the same is not well maintained. Hence, the Officer concerned was advised to instruct the beneficiary to maintain the pond so that the same will not get damage.